




1 see
no problem
with
this
kind of
arrangement
for the
end bay.

1994.11.F.40_3