

Structural Revision

Clarification

1. Lower Dining Hall finish floor 6". *Deleted*
- ✓ 3. Revise structural details of precast concrete arcade columns.
 - ✓ 4. Relocate foundation masonry wall in Dining Hall and revise reinforcing.
 - ✓ 5. Reinforcing steel for jog in arcade foundation at N.E. corner of Dining Hall.
 - ~~7B. Material and Details for Ledger Beam in Residential Building.~~
 - ✓ 8. Changes in second floor concrete beams in Residence Building.
 - ✓ 9. Specifications for strap anchors from wood beams to concrete beams.
 - 11. Change detail of wood beam support of columns detail C/R-13 *Revised #30*
 - 12. Connection detail of 6x12 beam at West end of Upstairs Arcade.
 - ✓ 13. Connection of masonry wall to concrete column at Entry Court.
 - ✓ 14. Footing and wall reinforcing details for masonry fence at Southern Boundary.
 - ✓ 16. Change wood stud dimension of Dayroom wall facing West Julian Street from 4x6 to 4x4.
 - ✓ 17. Delete 2x4 blocking for Roof Sheathing.
 - ✓ 19. Second Floor Residence Building wall sheathing to be applied to exterior of building in lieu of interior. Interior to be gypsum wall board.
 - ✓ 20. Details of 6x12 beam connection at lobby end of First Floor Arcade.
 - 21. Kitchen, Laundry, Shower Building foundation and masonry wall details. *DELETED*
 - 22. *DINING ROOM WALL SECTION @ WINDOWS REVISED PER #25*
 - ✓ 23. Details for concrete stair side entrances to Dining Hall. *DETAILS REVISED PER #36*
 - ✓ 24. Details of Gas Meter Box for Shower Building.
 - ✓ 25. Dining Hall masonry details.
 - ✓ 26. Connection of Kitchen to Dining Hall.
 - ~~28. Main Door and Window revisions Dining Hall~~
 - ✓ 29. Delete Seismic Joints in Residence Building.
 - ✓ 30. Beam sizes and connection details at First Floor Arcade.
 - ✓ 31. Provide attic ventilation Residence Building.
 - ✓ 32. Masonry lintel details at Entry Court.
 - ✓ 33. South wall exterior of Kitchen, Laundry, Shower Building to be texture 111.
 - ✓ 34. Attic ventilation and access in Kitchen, Laundry, Shower Building.
 - ✓ 36. Revisions to concrete steps and terrace in South Courtyard.
 - ✓ 37. Rafter connection to 6x12 beam at lobby and of first floor Arcade.
 - ✓ 42. Details of railing at second floor Arcade.
 - *EXTERIOR STAIR (See revised sht's R-16, R-16A)*